

#41607 WALL MOUNTED DIMMER WITH IR REMOTE



USER MANUAL

Working Temperature: -4 - 140 °F
 Supply Voltage: DC 12-24V
 External Dimensions: L876 x W876 x H41mm
 Max Load Current: 16A

Note: Connections should be made according to the wiring diagram. Output ground (-) should be isolated from the input ground (-) or dimming function will not work.

IR Remote Functions:

Symbol	Name of Key	Instructions
	ON/OFF	TURN DIMMER ON OR OFF
	DELAY OFF	DIMMER WILL TURN OFF IN 30 SECONDS
	BRIGHTNESS	PRESS AND HOLD TO ADJUST BRIGHTNESS UP OR DOWN
	HOTKEY	SELECT % OF BRIGHTNESS DESIRED
	PROGRAM PRESETS	PRESS BUTTON MORE THEN 3 SECONDS TO SAVE BRIGHTNESS LEVEL

Wiring Diagram

